Type L #Hits	규	Hits	Search Text	DBs	Time Stamp Comments.	Comments	Error Definition	Errors
BRS L1	L1	82	mop and (actuator same handle)	USPAT; US-PGPUB;2004/ EPO; JPO;10:48 DERWENT	USPAT; US-PGPUB;2004/08/16 EPO; JPO; DERWENT			0
BRS	1.2	Ō	USPAT; L1 and (actuator near15 US-PGPUB; 2004/08/16 compress\$4) DERWENT	USPAT; US-PGPUB;2004/ EPO; JPO;11:00 DERWENT	2004/08/16 11:00			0
BRS	L3	15	USPAT; Ll and (actuator near15 US-PGPUB; 2004/08/16 (fluid or liquid)) DERWENT	USPAT; US-PGPUB;2004/ EPO; JPO;11:01 DERWENT	2004/08/16 11:01			0
BRS	L4	15	USPAT; L1 and (actuator near15 US-PGPUB; 2004/08/16 valve) DERWENT	USPAT; US-PGPUB;2004/ EPO; JPO;11:02 DERWENT	2004/08/16 11:02			0